

Date: Tuesday, 3/11/2008 7:46:44 AM
User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : OH-58 SKIDTUBE
Job Number : 37707
Estimate Number : 11650
P.O. Number :
This Issue : 3/11/2008 S.O. No. :
Prsht Rev. : NC Part Number : D058672012
First Issue : 1 / Type : LANDING GEAR Drawing Number : N/A
Previous Run : 35352 Drawing Revision : N/A
Material :
Due Date : 3/31/2008 Qty: 1 Um: Each
Written By : JD 8.3.11
Checked & Approved By :
Comment : Est Rev:G 02.06.27 Re-format; CHG002 (MPP 2251); ECN 258K
J
Est Rev:H 07-03-08 As per IIN D058-672 Rev C jlm

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description :

1.0 DC DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Photo Copy Blue files and Type Labels as per PPP D058-672-012 CHG003

5 08/04/10 08/03/25

2.0 37707A OH-58 SKIDTUBE ASSEMBLY



Comment: Sub-Component 1 D058-672-041 OH-58 SKIDTUBE ASSEMBLY

37707A SP

3.0 PACKAGING 1 PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

4.0 D29332 206 Saddle Right



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2933-2 Saddle B36031

54

5.0 D29322 206 Saddle Right side



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2932-2 Saddle B35477

8/4/10 SP (1X)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:46:44 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OH-58 SKIDTUBE

Job Number: 37707

Part Number: D058672012

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

D2934

Saddle Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

2 D2934

Saddle Spacer

1334630

SP

7.0

D2935

Saddle Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

2 D2935

Saddle Spacer

1336142

SP

8.0

AN341A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

8 AN3-41A

Bolt

1106514

SP

9.0

D2652

Bushing



Comment: Qty.: 16.0000 Each(s)/Unit Total : 16.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch =

16 D2652

Bushing

37453

SP

10.0

AN960JD10

Washer



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

8 AN960JD10

Washer

1107334

SP

11.0

MS21042L3

Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

8 MS21042L3

Nut (or -3)

1106242

8/4/10

SP

(14)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:46:44 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OH-58 SKIDTUBE

Job Number: 37707

Part Number: D058672012

Job Number:



Seq. #:

Machine Or Operation:

Description:

12.0

AN510A

Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN5-10A Bolt

M107013

SP

13.0

AN512A

Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN5-12A Bolt

15204

SP

14.0

AN960JD516

Washer



Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 AN960JD516 Washer

M107008

SP

15.0

AN46A

Bolt



Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

12 AN4-6A Bolt

M105810

SP

16.0

AN960JD416

Washer



Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

24 AN960JD416 Washer

M106780

SP

17.0

MS21042L4

Nut



Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

M106825

8/4/9

SP

(1x)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:46:44 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OH-58 SKIDTUBE

Job Number: 37707

Part Number: D058672012

Job Number:



Seq. #:

Machine Or Operation:

Description :

12 MS21042L4 Nut (or -4)

18.0

D2712

Set Screw



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

10 D2712

Set Screw

34628

SP

19.0

D2968043

Tow Ring



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

1 D2968-043

Tow Ring

B32503

SP

20.0

AN960JD1016

Washer



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Washer

Batch:

SS19

SP

21.0

AN9704

Washer



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description

Batch

1 AN970-4

Washer

M107242

SP

22.0

MS210424

USE MS21042L4



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

USE MS21042L4

Batch:

M106825

SP

23.0

D058672043

GROUND HANDLING KIT



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

GROUND HANDLING KIT

BATCH:

B37841

8/4/9

SP (14)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:46:44 AM
User: Kim Johnston

Process Sheet

Customer: C0-DAR001 Dart Helicopters Services

Drawing Name: OH-58 SKIDTUBE

Job Number: 37707

Part Number: D058672012

Job Number:



Seq. #:

Machine Or Operation:

Description :

24.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

08/04/10

25.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D058-672-012

Location:

PPP Rev: *B*

08/04/10 (1)

26.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/04/14

Job Completion



mf 08-04-11

W

B37707A

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM
User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : 0H-58 SKIDTUBE ASSEMBLY
Job Number : 37707A
Estimate Number : 10475
P.O. Number :
This Issue : 3/11/2008 S.O. No. :
Prsht Rev. : NC Part Number : D058672041
First Issue : 1 / Type : LANDING GEAR Drawing Number : D2922 REV A1
Previous Run : 37706A Material :
Written By : JJO 8.3.11 Due Date : 3/31/2008 Qty: 1 Um: Each
Checked & Approved By :
Comment : Est Rev:C 02.06.28 Re-format; ECN 258 KJ
Est Rev:D 06.02.06 Added Dt8025 EC

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description:

1.0 DC DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Photocopy bluefile & type labels per PPP D058-672-041 CHG 001

N/A

2.0 D2620 Bent 206 Skidtube



Comment: Qty: 10000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number Description Batch
1 D2620 Bent Tube 3" OD

BE 08/03/26

BE 08/03/26

3.0 LANDING GEAR 1 LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Deburr Fwd edge of tube

BE 08/03/26

2-Weld D2794 cap as per QSI 004 and Dwg D2922 Use aluminum rod.

A/R Aluminum Rod

m1062330/m106762 BE 08/03/26

3-Cut aft end of D2620 bent tube as per dwg D2922

BE 08/03/27

4-Drill pilot holes using drill jig DT8480 and DT8025 open to 0.312" dia.

BE 08/03/27

5-Drill holes for wearplates using DT 8487 Open to 0.297" dia.

BE 08/03/27

6-Open holes for aft cap and tow ring as per Dwg D2922

BE 08/03/27

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 0H-58 SKIDTUBE ASSEMBLY

Job Number: 37707A

Part Number: D058672041

Job Number:



Seq. #:

Machine Or Operation:

Description :

8-Remove inner indexing ridge on aft end of skidtubeas per Dwg D2922

BE 08-03-27

9-Deburr and Blow out all chips form inside the tube

BE 08-03-27

4.0

QC5

INSPECT WORK TO CURRENT STEP



BE 08-03-27



Comment: INSPECT WORK TO CURRENT STEP

PD 08-03-27

①

5.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

PD 08-03-27

6.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

SL 08-03-27

7.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

BE 08-03-27

8.0

D2923

Web



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D2923

Web

3114

SL

8-3-27

9.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Open holes to finished size as per Dwg D2922(without cutting fluid)

2-Countersink crossbolt spacer holes as per Dwg D2922(without cutting fluid)

3-Deburr and Blow out all chips from inside the tube

4-Bond D2923 web in place as per QSI 015. Ensure holes lineup

A/R

Sikaflex-291

Sikaflex expire date: 8-7-31

107397

SL 8-3-27

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 0H-58 SKIDTUBE ASSEMBLY

Job Number: 37707A

Part Number: D058672041

Job Number:



Seq. #:

Machine Or Operation:

Description :

10.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

6 08/03/06

11.0

D2794

Cap



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Qty

Part Number

Description

Batch

1 D2794

Fwd Cap

R14588

BE

08/03/26

12.0

D2649

Crossbolt Spacer



Comment: Qty.: 22.0000 Each(s)/Unit Total : 22.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

22 D2649

Crossbolt spacer

37329

BE

08/04/01

13.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Weld D2649 cross bolt spacers as per QSI 004 and Dwg D2922.(Remember to back drill each hole to 0.250" before welding the other side)

A/R Aluminum Rod

m106330 BE 08/04/01

3-Grind welds flush as per Dwg D2922

4-Counterbore 5/16" x 0.750" deep as per Dwg D2922

75 674-1

14.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/04/02 (FL)

15.0

QC5

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

08/04/02 (FL)

16.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

Pressure wash m-p 08/04/07
m 107550

08-04-07

(1)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM

User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 0H-58 SKIDTUBE ASSEMBLY

Job Number: 37707A

Part Number: D058672041

Job Number:



Seq. #:

Machine Or Operation:

Description :

17.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



HL

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

08-04-07

(X)

18.0

D26483

Wearpad



Comment: Qty.: 5.0000 Each(s)/Unit Total : 5.0000 Each(s)

Pick:

Qty Part Number Description Batch

5 D2648-3 Wearpad 1333992

HL

19.0

D265615

Wearplate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D2656-15 Wearshoe 1334596

HL

20.0

D265621

Wearplate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D2656-21 Wearshoe 1333089

HL

21.0

D2924

Wearshoe



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D2924 Wearshoe 1335368

HL

22.0

MS27039108

Screw



Comment: Qty.: 50.0000 Each(s)/Unit Total : 50.0000 Each(s)

Pick:

Qty Part Number Description Batch

50 MS27039-1-08 Screw M106589

HL

08-04-07

(X)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 0H-58 SKIDTUBE ASSEMBLY

Job Number: 37707A

Part Number: D058672041

Job Number:



Seq. #:

Machine Or Operation:

Description:

23.0

AN960JD10L

Washer



Comment: Qty.: 50.0000 Each(s)/Unit Total: 50.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
50	AN960JD10L	Washer	M104885

gl

24.0

ALS41032130

Insert



Comment: Qty.: 50.0000 Each(s)/Unit Total: 50.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
50	ALS4-1032-130	Insert	M105854

or (see QSI 017)

gl

25.0

D26511

Plug



Comment: Qty.: 20.0000 Each(s)/Unit Total: 20.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
20	D2651-1	Plugs	B38273

x

gl

26.0

D26513

O-Ring



Comment: Qty.: 20.0000 Each(s)/Unit Total: 20.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
20	D2651-3	O-Rings	B36141

gl

27.0

D2646

Aft Cap



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
1	D2646	Aft Cap	B37755

gl 08.04.07 (40)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 0H-58 SKIDTUBE ASSEMBLY

Job Number: 37707A

Part Number: D058672041

Job Number:



Seq. #:

Machine Or Operation:

Description :

28.0

MS27039108

Screw



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 MS27039-1-08 Screw

M106589 21

29.0

AN960JD10L

Washer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 AN960JD10L Washer

M104885 21

30.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

1-Install inserts & wearpads as per dwg D2922. Insert a drop of Sikaflex at insert hole before installing wearplates.

A/R Sikaflex-291

M105585

Sikaflex expire date: 08/07

2-Install O-Rings D2651-3 on plugs D2651-1 with Petroleum Jelly and install plugs as per Dwg D2922

3-Install D2646 Aft Cap and seal with Sikaflex adhesive. Clean excess adhesive

A/R Sikaflex-291

M105585

Sikaflex expire date: 08/07

3- Wing Walk as per Dwg D2922 and QSI 005 4.4

M107385

21

08-04-08 (K)

Batch: M107385

31.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

32.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/04/09 (K)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 3/11/2008 7:47:00 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 0H-58 SKIDTUBE ASSEMBLY

Job Number: 37707A

Part Number: D058672041

Job Number:



Seq. #:

Machine Or Operation:

Description :

33.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

MP 37707 8/4/10 50 (H)

34.0

QC21

FINAL INSPECTION/W/O RELEASE



08/04/14 J

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



mf 08-04-10

U

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN RF	DRAWN BY RF	DART AEROSPACE USA, INC. BELLEVUE, WA	
CHECKED [Signature]	APPROVED [Signature]	DRAWING NO. D2922	REV. A SHEET 1 OF 2
DATE 99.10.14		TITLE OH-58 SKIDTUBE ASSEMBLY	SCALE NTS
A	99.10.14	NEW ISSUE	
A1	CP 01.08.20	φ0.640 WAS φ0.625	

RELEASED
00.05.11 [Signature]


Qty	Part Number	Description
X	D2922-041	SKIDTUBE ASSEMBLY
*	D2600-1	EXTRUSION
1	D2646	AFT CAP.
4	D2648-3	WEARPAD
1	D2648-5	WEARPAD
22	D2649	CROSS BOLT SPACER
20	D2651-1	PLUG
20	D2651-3	O-RING
1	D2656-15	WEARSHOE
1	D2656-21	WEARSHOE
1	D2794	CAP
1	D2923	WEB
1	D2924	WEARSHOE
50	AKS7-1032-130 or AKS4-1032-130 or ALS7-1032-130 or ALS4-1032-130	INSERT
52	AN960JD10L	WASHER
52	MS27039-1-08	SCREW

GENERAL NOTES:


- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) LENGTH OF D2600-1 EXTRUSION REQUIRED BEFORE BENDING = 160 INCHES.*
- 3) INSERT D2923 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241/291 ADHESIVE PER DART QSI 015 AFTER BENDING.
- 4) USE DART DRILL TEMPLATE DT8406 TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL AKS7-1032-130 PER SECTION D-D (50 PLACES) AFTER FINISH. INSTALL MS27039-1-08 SCREWS AND AN960JD10L WASHERS IN ALL INSERTS. SEAL WITH SIKAFLEX-241/291.
- 5) WELDING TO BE DONE PER DART QSI 004.
- 6) FINISH:
ACID ETCH, ALODINE PER DART QSI 005 4.1 PRIOR TO INSERTING D2923 WEB
POWDER COAT ASSEMBLY GLOSS WHITE (REF 4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED TO 0.50 ABOVE LOCATION RIDGE PER DART QSI 005 4.4
- 7) INSERT D2651-1 PLUG C/W D2651-3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE) AFTER FINISH (20 PLACES).

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 371071


DETAIL A
SCALE 1:4




DETAIL B
SCALE 1:4



DETAIL C
SCALE 1:4



SECTION D-D
SCALE 1:4
FOR 0.375 HOLES ONLY




- AFTER BENDING AND DRILLING ASSEMBLY PERFORM THE FOLLOWING FOR 0.375 HOLES ONLY:
1. CHAMFER HOLE 0.030 X 45°
 2. INSERT D2649 SPACER (22 PLACES)
 3. WELD INTO PLACE AND GRIND FLUSH
 4. C'BORE D2649 SPACER TO 0.313 X 0.75 DEEP


AKS7-1032-130 (REF)
(TYP 50 PLACES)

RELEASED
00.05.11


D2922-1 BENDING DETAIL



D2922-1 DRILLING DETAIL




D2922-041 ASSEMBLY DETAIL



DESIGN RF	DRAWN BY RF	DART DART AEROSPACE USA, INC. BELLEVUE, WA	REV. A
CHECKED [Signature]	APPROVED [Signature]	DRAWING NO. D2922	SHEET 2 OF 2
DATE 99.10.14		TITLE OH-58 SKIDTUBE ASSEMBLY	SCALE 1:20

NO WORK ORDER
3740314
SUBJECT TO ELEMENT
WITHOUT NOTICE
UNCONTROLLED COPY
ENGINEERING
RETURN TO
SHOP COPY



NO. 146

AWS D17.1.2001
QUALIFICATION TEST RECORD

Name: Barclay Elliot
Job number: 37704A
Part number: D058-62-041
Description: OH-SG skid tube
Welding Process: Tig ☒ Mig ☐
Base material: Aluminium
Current: AC ☒ DC ☐

TEST REQUIREMENTS AND RESULTS

Visual: pass ☒ fail ☐
Penetration: pass ☒ fail ☐

UNACCEPTABLE

Cracks: pass ☒ fail ☐
Undercut: pass ☒ fail ☐
Pin holes: pass ☒ fail ☐
Overlap (cold lap): pass ☒ fail ☐
Porosity (surface): pass ☒ fail ☐
Coloration: pass ☒ fail ☐

Qualifier Pet. Duval Date of Test Coupon 08-03-28
Welder Barclay Elliot Date of Test Coupon 08-03-28

The above named individual is qualified in accordance with AWS D17.1.2001 to weld